ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	6	Thanisandra
Street ID	**Street Name**	**Significant Landmark**
W0517, W0523, W0511, W0507	NA, I T P L Main Rd	Maruth Layout
Segment No.	**Total Length (m)**	
6/C-W0517/S035225	354.52	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	81.60	77.606712	13.058017	77.606643	13.057283	W0346	W0523
2	81.94	77.607043	13.058024	77.606977	13.057286	W0346	W0523
3	190.98	77.607339	13.058038	77.606309	13.057243	W0346	W0507

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvement to Roads and Drains at Left hand Side of Maruth Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	3000000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Improvement to Roads and Drains at Left hand Side of Maruth Layout in ward no 06 Byatarayanapura Sub-Division Yelahanka zone	006-15-000024
Work Order No.	**Work Order Date**	**Period of Extention**
BBMP/EE/BTP/WO/08/2015-16	30/04/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
30/04/2016	29/04/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
NITHIN.R		0.00
Phone No.	**E-Mail ID**	
9341260169		

Field Inspection Details

Number of Trees	Any Other Information	Name
8		KRISHNAPPA

Date of Inspection	Remarks
26/11/2016	COMPLETED

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0517, W0523, W0511, W0507

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	26/11/2016	26/12/2016	COMPLETED
SE	VASU K M	26/11/2016	26/12/2016	COMPLETED
EE	YARAPPA REDDY	26/11/2016	26/12/2016	COMPLETED
AEE	J N LOKESH	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED
AE	KRISHNAPPA	26/11/2016	26/12/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0517, W0523, W0511, W0507